

















POWERPS SONIC®

SLA Batteries PS, PSG, PSH and PG Series Terminal Details

| | | | |
|---|--|---|---|
| F1  FASTON 0.187" x 0.032" quick disconnect tabs. | WL INSULATED WIRE LEADS <ul style="list-style-type: none"> Molex Housing 5264-02 & 5263-PBT plug on PS-605 AMP Housing 1-480318-0 & 8116-1 on PS-1208 | NB1  Torque: 2.0~3.0 Nxm | B, T6 THREADED INSERT - 6mm STUD  Torque: 3.9~5.4 Nxm |
| F2  FASTON 0.250" x 0.032" quick disconnect tabs | PC PRESSURE CONTACTS | NB2  Torque: 3.9~5.4 Nxm | T8 THREADED INSERT - 6mm STUD  Torque: 3.9~5.4 Nxm |
| FP  FASTON POLARIZED Positive: "F2", Negative: "F1" | TH  TOY BATTERY CONNECTORS H-connector PS-6120 TH | NB3  Torque: 3.9~5.4 Nxm | T11 THREADED INSERT - 8mm STUD  Torque: 11.0~14.7 Nxm |
| F1/0  6 4.8 21 ±0.6 | TS  TOY BATTERY CONNECTORS S-connector PS-6120 TS | NB4  Torque: 3.9~5.4 Nxm | T12 THREADED INSERT - 5mm STUD  Torque: 2.0~3.0 Nxm |
| SP  SPRING TERMINALS Fully collapsible positive and negative contacts | U  Positive: 17.4, 18, 22, 19 Negative: 15.9, 18, 22, 17.5 Torque: 11.0~14.7 Nxm | | |